



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor

Robert L. Morgan
Executive Director

Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210

PO Box 145801

Salt Lake City, Utah 84114-5801

(801) 538-5340 telephone

(801) 359-3940 fax

(801) 538-7223 TTY

www.nr.utah.gov

August 13, 2002

TO: Minerals File

FROM: Doug Jensen, Senior Reclamation Specialist *D. Jensen*

RE: Site Inspection, Preston Hafen, Rhyolite #1 Project, S/021/032, Iron County, Utah

Date of Inspection: July 16, 2002
Time of Inspection: 11:45 p.m.
Conditions: Cloudy & Warm
Participants: Doug Jensen, DOGM

Purpose of Inspection: To become familiar with the site.

Getting to the site:

This site is located approximately three miles west of Beryl Junction near Highway 56.

Observations:

The site is small with what appears to be an area that has been blasted. A small amount (~50 to 100 tons) of the blasted material has been removed and approximately that amount of blasted rock remains to be removed. There was no equipment on the site, it appeared that the site had not been utilized recently.

Conclusions and Recommendations:

I found no environmental concerns with the site but I did not see the t-posts that were requested to outline the permitted area. Due to prior commitments and time constraints, no photos or GPS files were created while on the site.

jb

CC: Ed Ginouves, BLM, Cedar City FO, (UTU-79327)

Preston Hafen, Operator

Doug Jensen, DOGM

O:\M021-Iron\S0210032-RhyoliteQuarry\Final\ins-7-16-02.doc